

Tree Condition Report

Location of property:

Bramley Meade Hall
Wiswell lane
Whalley
BB7 9AF

Arboricultural report for:

Jeremy Ashby

Date of site survey:

03/02/2025

Date of report:

09/02/2025

Job Ref: 2092

Survey undertaken by:

Gary Marsden
FDS Arb, M.Arbor.A.




The content and format of this report are for the exclusive use of the client. It may not be sold, lent, hired out or divulged to any third party not directly involved in this subject matter without our written consent.

I hope that this report provides all the necessary information, but should any further advice be needed please do not hesitate to contact me.

Any enquiries regarding this report should be addressed to:

GM Tree Consultants Ltd
16, Farfield Drive,
Lower Darwen,
Darwen,
Lancashire,
England,
BB3 0RJ.



Gary Marsden FDS Arb M.Arbor.A

Professional Member - Arboricultural Association (AA)

Professional Member - Consulting Arborist Society (CAS)



Contents

Introduction	4
Limitations.....	5
Site visit and observations.....	6
Condition assessment	8
Recommendations	12
Other Considerations	13
APPENDIX 'A'	16
APPENDIX 'B'	17
Back cover	18

Introduction

1. Qualifications and experience.

- 1.1. I have based this report on my site observations and any provided information, and I have come to conclusions in the light of my 25+ years' experience in the arboricultural industry. I have professional indemnity and public liability insurance at the required level to undertake such work.

2. Instruction.

- 2.1. I am instructed by Jeremy Ashby (referred to as the 'client' from here on) to inspect two significant trees located , at Bramley Meade Hall, Wiswell lane, Whalley, BB7 9AF and to provide a report to fulfil the following criteria:

- A schedule of the relevant tree to include basic data, tree location and a condition assessment.
- A tree risk assessment based on relevant targets, defects, and likelihood of failure.
- A schedule of any subsequent work that may be required.
- Complete an application form to work on protected trees and submit this to the relevant local authority with the report as supplementary evidence.

3. Relevant background information.

- 3.1. Prior to the tree inspection, my client advised me that a survey of the trees is needed to assess their condition and make any recommendations with regards to managing the trees.

4. Documents and information provided.

- 4.1. My client provided me with copies of the following documents or information:

- Their email of instruction outlining the situation.
- Their email commissioning this report and agreeing to the T&C and cost.

5. Scope of this report.

- 5.1. This report is only concerned with the prominent trees within or around the proximity of the site. It takes no account of any trees outside this remit or any building structural issues. It includes a preliminary assessment based on the site visit and any documents and information provided, listed in section 3 and 4 above.

- 5.2. The survey is based upon information that was available at the time of the inspection. Further inspections are necessary over time to give a fuller picture of the health of trees.

6. Mapping.

- 6.1. I have not been provided with a topographical survey of the site. A digital ordnance survey map has been purchased, and I have plotted the trees by the combined / individual use of land

features, manual measurements, laser measurements and GPS. It is estimated that the accuracy is within 1-2m.

6.2. Site plans showing all the tree locations and any relevant details can be found in Appendix 'B'.

7. Tree health.

7.1. This arboricultural report is based on the following primary technical references:

- British Standards Institution (2010) BS 3998 Recommendations for tree work
- Lonsdale, D. 1999. *Principles of Tree Hazard Assessment and Management*. The Stationary Office, London.
- Lonsdale, D. 2000. *Hazards from trees. A general guide*. Forestry Commission, Edinburgh.
- Matheny, N. P., and Clark, J.R. *A photographic guide to the evaluation of hazard trees in urban areas. 2nd Edition*. International Society of Arboriculture.
- Mattheck, C, and Breloer, H. *The body language of trees – A handbook for failure analysis*. The Stationary Office, London.
- Schwarze, F.W.M.R., Engels, J. and Mattheck, C. *Fungal strategies of wood decay in trees*. Springer, Berlin.
- Strouts, R.G. and Winter, T.G. 1994. *Diagnosis of ill-health in trees*. The Stationary Office, London.
- The National Tree Safety Group. 2011. *Common sense risk management of trees. Guidance on trees and public safety on the UK for owners, managers, and advisers*. Forestry Commission, Edinburgh.

Limitations

8. Survey.

8.1. The inspection was carried out from ground level only and relates only to arboricultural aspects. All visual observations and recommendations relate to the condition of the trees on the day of the survey. The trees have been assessed with the aid of a Nylon mallet for detecting changes in resonance which may indicate that further investigation is required. Where appropriate the use of advanced decay detection methods is used, primarily a digital resitograph. Any unusual weather conditions, changes in soil, soil levels and changes to surroundings may result in a dramatic change in the trees health.

9. Time limit.

9.1. Due to the changing nature of trees and other site circumstances, this report and any recommendations made are limited to a 24-month period. Any alteration to the site and any development proposals could change the current circumstances and may invalidate this report and any recommendations made.

10. Tree health.

- 10.1. Trees are dynamic structures that can never be guaranteed 100% safe: even in good condition they can suffer damage under average conditions. Regular inspections can help to identify potential problems before they become acute.

11. Justification of works.

- 11.1. Where management action / tree surgery is recommended, this is based on maximizing the tree's safe useful life expectancy (SULE), given its current situation or the safety of persons and surrounding targets. A lack of recommended work does not imply that a tree is safe and likewise it should not be implied that a tree would be made safe following the completion of any recommended work.

12. Buildings.

- 12.1. This report does not consider the structural condition of existing buildings, nor the impact of existing trees on their foundations. If there are concerns over such matters the advice of a structural engineer should be sought.

Site visit and observations

13. Site visit.

- 13.1. I carried out an unaccompanied site survey on 03/02/2025. All my visual observations were undertaken from within the clients' boundaries or publicly accessible areas from ground level, and I estimated all dimensions unless otherwise indicated. An assessment was carried out using a Resistograph to help determine the internal qualities of a tree as visual indicators prompted further investigation. The weather at the time of inspection was clear, still, , and dry, with good visibility.

14. Brief site description.

- 14.1. The site consists of a residential property that is currently occupied and centrally set within the site boundary, the pine tree is located outside the client's fenced boundary but is on land responsible by the client. No significant utility services were observed on site. No visual inspections of any services were made below ground level. There is no known history on this site either personal or from a third party.

15. Identification and location of the trees.

- 15.1. I have illustrated the locations of the significant trees on the map included in Appendix 'B'. This plan is for illustrative purposes only and it should not be used for directly scaling measurements. All the relevant information on it is contained within this report and the provided documents.

16. Systematic method of assessment.

- 16.1. I visually inspected the significant trees and recorded the information in the table in section 18.
- 16.2. This inspection was of a preliminary visual tree assessment (VTA) nature that was visible from accessible points at ground level, and I also included detailed investigation with the use of a

resistograph to assess the internal function of the stem / buttress / roots area, and an aerial assessment using ropes and harness to access the canopy of the tree.

16.3. The methodology employed in the assessment of trees undertaken by GM Tree Consultants Ltd takes into consideration the following points (but not in any order of importance) by firstly carrying out a Visual Tree Assessment (VTA), this includes:

- A distance visual assessment of the tree considering the overall shape, form, foliage colour appropriate for the time of year and any other elements that do not appear normal for that species.
- The exposure to the weather. This can be due to it being a solitary tree or that surrounding tree cover could have been removed exposing it to 'new wind forces' acting on the canopy.
- The prevailing ground conditions. For example: soil erosion, ponding, soil characteristics and the impact on the tree, presence / lack of vegetation.
- Any information as to the tree's history or history of the surrounding trees / landscape. For example: previously failed limbs, surrounding tree removal / failure, excavations, fruiting bodies seen.
- Knowledge of previous documented information of issues with a species. For example: tight union failure on Beech, poor compartmentalisation of Willow.
- The health and visual defects of the tree. For example: cavities, the trees 'body language', dieback, foliage irregularities, fungal brackets, and deadwood.

16.4. From this information an assessment is made of the likelihood of the part/s most likely to fail in relation to the target / occupancy value within the trees failure area and recommendations are then made, these can include the following but is not exhaustive:


- Recommendations for further visual monitoring.
- Investigation with more advanced decay detection equipment such as: Resistograph, Picus, Thermal imaging.
- Remedial pruning / limb removal.
- Whole tree removal.
- Pruning for aesthetical reasons.
- Removal of significant deadwood.
- Or no work may be needed.

16.5. The primary reasoning behind this method of assessment is to identify a foreseeable failure, make an informed decision and act on it within a specified time and know that the response is reasonable in relation to the target area and the financial resources available.

17. Resistograph .

17.1. Where there is external visual indication of possible dysfunction or concern over its condition within a section of stem / branch, a drill test using a Resi-PD400 has been carried out to gain more information as to the quality of the internal structural wood.

- 17.2. The IML-RESI PowerDrill® (Resi-PD400) measures the drilling resistance and feed force of the wood to supply the user with data to make a clear statement about the condition of the wood.



- 17.3. With a fine drilling needle, the measuring device penetrates the wood in a minimally invasive way and records both the drilling resistance and the feed force in relation to the penetration depth. When the bit enters a void or decay, the measurement curve will lose resistance and be seen as a flat or decreasing line in the graph clearly defining a loss in wood structure.
- 17.4. Each measurement graph will have an Assessment box which shows conditions and the depth (cm) of which that condition applies, this correlates to the colour above and below the graph, these graphs are inserted in Appendix 'B'.

Colour codes on Resi-PD400 assessment graph	
Bark	Cavity
Structural wood	Split
Partial decay	Abnormal density
Decay	Drill exited tree
Extensive decay	Drill retraction

Condition assessment

18. Tree dimensions.

- 18.1. A detailed on-site assessment of the trees can be found in the inserted survey sheets in appendix 'B'.

19. Tree assessment summary.

- 19.1. The tree data and any identified works are shown in the tree schedule any recommended works should be carried out within the identified timeframes, giving priority to any tree highlighted as a safety concern.
- 19.2. The Lime tree T001, has internal decay within the stem that has the potential to lead to a whole tree failure due to the reduced strength and ability to support the upper framework of the mature tree canopy, the internal qualities of the stem have been clarified using a resistograph.
- 19.3. Removal of T001 to ground level is recommended on safety grounds as there is a residential property, garage, driveway and garden area within the target area of the tree.

- 19.4. Within 2m of the mature pine tree, T002, a trench has been previously dug to a depth of approximately 1m where severed roots can be seen, see photos, this appears to be some form of land drainage as the trench leads to what appears to be a drain on the roadside of the wall. The client informed me that he does know who or when the trench was dug.
- 19.5. The tree has an already restricted rooting area due to the road and the difference in ground levels. The tree is circa 23m in height with occupied residential properties and a busy road within the trees target area.
- 19.6. My concern is that due to the recent root severance and existing restricted rooting area constraints, there is a foreseeable risk that the tree could suffer a whole tree failure in high winds due to the height and canopy spread of the tree, with high-risk targets where the tree could land.
- 19.7. Removal of T002 to ground level is recommended on safety grounds as there is residential properties, driveway, garden and road area within the target area of the tree.

20. Photos.

- 20.1. Below are photographs of relevant trees to aid in identification of any notable defects or required tree management actions.


T001 – Lime tree with decay in the stem and within falling distance of residential property.





T002 – Pine tree with root severance – photos showing trench and tree in reference to surrounding target areas.





20.2. I have taken additional photographs of the site for reference, and these are kept on file; these can be used to compare the condition of trees in future re-surveys; photos are added into the report only if they are needed to highlight a specific issue.

20.3. A copy of all photos taken on site can be sent as a link to an online cloud folder, please ask for a link to be emailed to you, if required.

21. Target led tree risk assessment.

21.1. Each tree was assessed for defects / dysfunction that could lead to part of or whole tree failure / breakage. With this an assessment is made as to where the tree / part of tree would land if that defect failure occurred and what the likelihood and consequence would be if this happened.

22. Appropriate Response.

22.1. From the risk assessment, recommendations are made to reduce the risk of harm to an acceptable level and within an appropriate timescale, this could be pruning works, further advanced investigations, more monitoring at specified intervals or ultimately removal of the tree, this list is not exhaustive and is adaptable to each individual situation.

22.2. REASONING: "Proactive intervention rather than reactive to failure"

Recommendations

23. Present requirements.

23.1. Any works required to establish acceptable levels of risk for the site and to maintain the tree in line with good arboricultural management are listed and should be carried out within the time scale indicated.

23.2. These lists of works are designed to highlight dangerous situations and are necessary for safety reasons or to establish high levels of arboricultural management to the existing tree.

23.3. All works listed in the tree survey schedule 'Recommendations' column must be carried out within the recommended timescale.

24. Re-survey.

24.1. It is important to follow up with any recommended re-surveys / follow-up inspections of trees detailed in this report, failure to schedule a resurvey could lead to a potential issue being overlooked and a tree failure averted.

24.2. There are several reasons why a re-survey is recommended, these could be (list not exhaustive):

- Ongoing future tree management.
- Monitoring of potential health and safety concerns.
- Carry out a climbing assessment of the upper canopy to assess a potential defect.
- Carry out advanced decay detection such as resistograph testing.
- The tree wasn't in leaf at the time of inspection and a further assessment is need when in leaf, normally during the summer.
- To determine the health / vitality of the tree.
- Determine the potential presence of a disease such as 'Ash Dieback'.
- Analyse a potential fungal bracket when fully developed, normally during autumn / winter season.
- Ensure recommended works have been undertaken and to the correct standard by a contractor.

Other Considerations

25. Tree Preservation Order (TPO) and Conservation Area (CA).

- 25.1. A tree preservation order, referred to as a 'TPO', is an order made by a local planning authority ('LPA') in respect of trees or woodlands.
- 25.2. The principal effect of a TPO is to prohibit the: Cutting down, uprooting, topping, lopping, wilful damage, or wilful destruction of trees without the LPAs consent. The cutting of roots is potentially damaging and so, in the Secretary of State's view, requires the LPAs consent.
- 25.3. Anyone who, in contravention of a TPO, wilfully damages a tree in a way that is likely to destroy it is guilty of an offence. Anyone found guilty of this offence is liable, if convicted in the Magistrates Court, to a fine of up to £20,000. In serious cases a person may be committed for trial in the Crown Court and, if convicted, is liable to an unlimited fine.
- 25.4. Conservation Areas are areas of special architectural or historical interest with a character or appearance that is desirable to preserve or enhance. Trees may often contribute to the special character of the area.
- 25.5. All trees in a Conservation Area are subject to controls which enable the LPA to protect the special character of the area created by the trees. If trees have a specific Tree Preservation Order (TPO) on them, then the normal Tree Preservation Order controls apply.
- 25.6. You must give the LPA 6 weeks' notice, in writing, of your intention to do any work to trees in a Conservation Area. You must not carry out any work during the six-week period, which starts from the date of receipt of your notification by the council, unless you receive written permission to do so.
- 25.7. Work which is not exempt and is carried out without formal notification or within the six-week period without the written consent of the council is illegal. The LPA may prosecute offenders and fines of up to £20,000 for each tree may be imposed by the Magistrates Court in the event of offenders being convicted of an offence. If proceedings are instituted in the Crown Court fines are unlimited. There is a duty to replace any tree removed without permission.
- 25.8. *At the time of writing this report it has been confirmed by the client that there is a Tree Preservation Order / Conservation Area in force on some or all the trees in question. It is strongly advised that prior to undertaking any work on the tree/s written consent is granted from the local authority via an application or through the planning process.***

26. Local authority details.

26.1. For reference the contact details are listed below for the relevant councils planning department and / or the arboricultural (tree) officer.

Ribble Valley Borough Council
Council Offices,
Church Walk,
Clitheroe,
Lancashire,
BB7 2RA
Tel: 01200 425111,
E-mail: webmaster@ribblevalley.gov.uk

27. Correspondence with local arboricultural / planning officer.

27.1. There is no significant correspondence that needs documenting into this report.

28. Tree works.

28.1. The management options noted in the survey data should be followed so to keep a maintained tree stock on and around this development site, particularly giving clearance from properties and over any adopted roads or footpaths.

29. Implementation of works.

29.1. All tree works should be carried out to BS 3998 Recommendations for Tree Work as modified by more recent research. It is advisable to select a contractor from the local authority list and preferably one approved by the Arboricultural Association. Their Register of Contractors is available free from:

Arboricultural Association The Malthouse, Stroud Green, Standish, Stonehouse, Gloucestershire GL10 3DL, UK	Tel: +44 (0)1242 522152 Email: admin@trees.org.uk Website: http://www.trees.org.uk/ARB-Approved-Contractor-Directory
--	--

30. Local Arboricultural Contractors.

30.1. If requested, I can provide a list of reputable arboricultural contractors that have carried out work on previous projects.

31. Safety.

31.1. Tree works can be a hazardous profession, so it is important that all operatives have the necessary and relevant training, health and safety policy and valid forms of insurance.


32. Statutory wildlife obligations.

- 32.1. The Wildlife and Countryside Act 1981 as amended by the Countryside and Rights of Way Act 2000, provide statutory protection to birds, bats and other species that inhabit trees. All tree work operations are covered by these provisions and advice from an ecologist must be obtained before undertaking any works that might constitute an offence.

33. Future considerations.

- 33.1. Any remaining trees should be inspected on a regular basis by a qualified arboricultural consultant and should not exceed a 5-year interval.

APPENDIX 'A'

- Estimate of site location boundary aerial photo taken from Google Maps showing site location. 



APPENDIX 'B'


- Tree location plan with corresponding tree numbers to aid identification.
- Inserted tree schedule showing all surveyed trees with comments and recommendations.
- Inserted resistograph test results.

Bramley Meade Hall,
Wiswell Lane,
Whalley,
BB7 9AF

VTA assessment of 2x trees - Ref: 2092


Page size: A3

1 : 600




GMTREE
CONSULTANTS



Job Ref:	2092		Survey Date:		03-Feb-2025			Surveyor:		Gary Marsden			Site Address:		Bramley Meade Hall			VTA site survey			
Type	Ref.	Species	Number of stems	Stem diameter @ 1.5m (cm)	Height	Spread	Life Stage	Physiological Condition	Structural Condition	Life Expectancy	Survey Notes	Fungus	Pests and Diseases	Description	Is RISK 'ALARP' As Low As Reasonably Practicable	Recommendations	Timescale for recommended works	Re-inspect within			
Tree	T001	Common lime (<i>Tilia x vulgaris</i>)	1	77	20	N:5 E:5 S:5 W:5	Mature	Fair	1 1 1 Decaying	<10 years	<ul style="list-style-type: none">_ Detailed inspection undertaken - 3 resitograph tests taken at buttress and stem area._ resonance test with nylon hammer indicates decay / hollow internal properties.<ul style="list-style-type: none">_ Stem decay._ Hollow Stem._ Moderate deadwood 25-100 mm diameter.<ul style="list-style-type: none">_ Crown dieback._ Thinning crown._ Seasonal leaf drop has occurred._ Tree not in leaf (normal).	No significant visible fungus present at the time of inspection.	No significant visible Pests or Disease present at the time of inspection.	Owned by the client. Target # - Dwelling Target # - Garden Target # - Parking / driveway Target # - Garage Target # - Open Space	NO	<ul style="list-style-type: none">_ Remove tree to ground level for arboricultural management reasons._ Stump grind.	03-May-2025 (3 Months)	Not Applicable			
Tree	T002	Not identified (<i>Not identified</i>)	1	97	23	N:7 E:7 S:7 W:7	Mature	Fair	Poor	<10 years	<ul style="list-style-type: none">_ Restricted Rooting Volume._ Cut/Damaged roots, XX (m) from stem._ No significant visual stem defects._ No significant visual branch defects._ Minor deadwood <25 mm diameter._ Abnormal foliage density._ Tip dieback.	No significant visible fungus present at the time of inspection.	No significant visible Pests or Disease present at the time of inspection.	Owned by the client. Roadside tree. Target # - Road Target # - Footpath - highway Target # - Dwelling Target # - Garden Target # - Parking / driveway Target # - Garage	NO	<ul style="list-style-type: none">_ Remove tree to ground level for arboricultural management reasons._ Stump grind.	03-May-2025 (3 Months)	Not Applicable			

Measuring / object data

Measurement no.:	4	Speed	: 2500 r/min	Diameter:	60.00 cm
ID number	: T1-LIME-	Needle state:	---	Level	: 1m
Drilling depth	: 40.01 cm	Tilt	: ---	Direction:	South
Date	: 03.02.2025	Offset	: 185 / 546	Species	: Lime
Time	: 11:04:39	Avg. curve	: off / off	Location	:
Feed	: 200 cm/min	Name	:		



Assessment


From	0.03 cm	to	0.58 cm	:	Bark
From	0.58 cm	to	3.90 cm	:	Decay
From	3.90 cm	to	33.64 cm	:	Partial decay
From	33.64 cm	to	35.30 cm	:	Decay
From	35.30 cm	to	39.86 cm	:	Partial decay

Comment

internal decay / dysfunction present.

Measuring / object data

Measurement no.:	5	Speed	: 2500 r/min	Diameter:	
ID number	: T1-LIME-	Needle state:	---	Level	: 0.5m
Drilling depth	: 29.70 cm	Tilt	: ---	Direction:	North
Date	: 03.02.2025	Offset	: 141 / 554	Species	: Lime
Time	: 11:05:15	Avg. curve	: off / off	Location	:
Feed	: 200 cm/min	Name	:		



Assessment


From 0.08 cm to 1.41 cm	: Bark
From 1.41 cm to 22.83 cm	: Partial decay
From 22.83 cm to 24.60 cm	: Decay
From 24.60 cm to 29.72 cm	: Extensive decay
From 29.72 cm to 33.00 cm	: Cavity
From 33.00 cm to 40.00 cm	: Drill retraction

Comment

Extensive decay present at 24cm with the automatic needle retraction at 30cm due to cavity

Measuring / object data

Measurement no.:	9	Speed	: 2500 r/min	Diameter:	
ID number	: T1-LIME-TEST	Needle state:	---	Level	: 1m
Drilling depth	: 40.01 cm	Tilt	: ---	Direction:	North
Date	: 03.02.2025	Offset	: 140 / 318	Species	: Test tree - Lime
Time	: 11:08:33	Avg. curve	: off / off	Location	:
Feed	: 200 cm/min	Name	:		



Assessment

- From 0.03 cm to 2.29 cm : Bark
- From 2.29 cm to 39.93 cm : Structural wood

Comment

This test drilling on a healthy Lime tree on site shows the expected resistance graph of structural wood.

BS 5837 Surveys

**Arboricultural Impact
Assessments**

**Arboricultural Method
Statements**

Site Supervision

Visual Tree Assessments

QTRA Assessments

Expert Witness Reports

**L.O.L.E.R Thorough
Equipment Inspections**

Mortgage Reports

TPO applications and advice

