


Photographic Record – Hurst Green Guild Hall Social Club

320110528P

Entrance Lobby




Photograph 1 – View from main entrance door looking into entrance corridor / lobby




Photograph 2 –Ceiling to entrance lobby

320110528P




Photograph 3 – Beam at ceiling level (believed to be timber with plasterboard boxing)



Photograph 4 – Modern timber door to cupboard

320110528P



Photograph 5 – Modern timber door to meeting room



Photograph 6 – Wall between corridor and meeting room [NOTE: THIS IS THE WALL WHICH IS PROPOSED TO BE REMOVED]

320110528P



Photograph 7 – Internal face of external wall to front elevation



Photograph 8 – Main entrance timber door / sheet vinyl floor finish

320110528P

Toilet



Photograph 9 – Ceramic wc, with existing foul drainage in corner behind boxing




Photograph 10 – Internal face of external wall to right side elevation, uPVC double glazed window

320110528P



Photograph 11 – Ceramic wash hand basin



Photograph 12 – Wall beneath staircase

320110528P



Photograph 13 – Modern timber door to toilet

Meeting Room



Photograph 14 – Internal face of front elevation wall, floor joists above with plasterboard boxing

320110528P




Photograph 15 – Dry-lining to internal face of external wall to left side elevation, uPVC double glazed window




Photograph 16 – Dry-lining to internal face of external wall to left side elevation

320110528P



Photograph 17 - Dry lined internal wall between meeting room and store room



Photograph 18 -- Internal wall between staircase / cupboard / corridor [NOTE: THIS IS THE WALL WHICH IS PROPOSED TO BE REMOVED]

320110528P



Photograph 19 - Modern timber door leading to staircase




Photograph 20 – Internal wall between staircase / cupboard / corridor [NOTE: THIS IS THE WALL WHICH IS PROPOSED TO BE REMOVED]

320110528P

Store Room




Photograph 21 – Junction of internal wall to meeting room and external wall to left side elevation where window is situated




Photograph 22 – Existing uPVC window to left side elevation

320110528P



Photograph 23 – Internal wall between store room and Guild Cottage (the existing dwelling) to the left side of the storeroom



Photograph 24 – Internal wall between store room and Guild Cottage (the existing dwelling) to the rear of the storeroom



320110528P

Photograph 25 – Internal wall between store room and Guild Cottage (the existing dwelling) to the rear of the storeroom



Photograph 26 - Internal wall between store room and the bottle room of the club to the right side of the storeroom

320110528P



Photograph 27 – Existing original timber floor joist




Photograph 28 – Existing timber floor boards



Photograph 29 – Rotten floor proposed to be repaired like for like

320110528P



Photograph 30 – Left Side Elevation

320110528P



Photograph 31 – Front Elevation

320110528P



Photograph 32 – Right Side Elevation