


Photographic Record – Hurst Green Guild Hall Social Club

Entrance Lobby




320110529P

Photograph 1 – View from main entrance door looking into entrance corridor / lobby



Photograph 2 –Ceiling to entrance lobby




320110529P

Photograph 3 – Beam at ceiling level (believed to be timber with plasterboard boxing)



Photograph 4 – Modern timber door to cupboard



320110529.p

Photograph 5 – Modern timber door to meeting room



Photograph 6 – Wall between corridor and meeting room [NOTE: THIS IS THE WALL WHICH IS PROPOSED TO BE REMOVED]



320110529P

Photograph 7 – Internal face of external wall to front elevation



Photograph 8 – Main entrance timber door / sheet vinyl floor finish

Toilet



320110529P


Photograph 9 – Ceramic wc, with existing foul drainage in corner behind boxing



Photograph 10 – Internal face of external wall to right side elevation, uPVC double glazed window



Photograph 11 – Ceramic wash hand basin



Photograph 12 – Wall beneath staircase

320110529P




Photograph 13 – Modern timber door to toilet

320110529P

Meeting Room



Photograph 14 – Internal face of front elevation wall, floor joists above with plasterboard boxing




320110529P

Photograph 15 – Dry-lining to internal face of external wall to left side elevation, uPVC double glazed window




Photograph 16 – Dry-lining to internal face of external wall to left side elevation



320110529P

Photograph 17 - Dry lined internal wall between meeting room and store room



Photograph 18 – Internal wall between staircase / cupboard / corridor [NOTE: THIS IS THE WALL WHICH IS PROPOSED TO BE REMOVED]



320110529P

Photograph 19 - Modern timber door leading to staircase




Photograph 20 – Internal wall between staircase / cupboard / corridor [NOTE: THIS IS THE WALL WHICH IS PROPOSED TO BE REMOVED]

Store Room




320110529P

Photograph 21 – Junction of internal wall to meeting room and external wall to left side elevation where window is situated




Photograph 22 – Existing uPVC window to left side elevation




320110529P

Photograph 23 – Internal wall between store room and Guild Cottage (the existing dwelling) to the left side of the storeroom




Photograph 24 – Internal wall between store room and Guild Cottage (the existing dwelling) to the rear of the storeroom



20110529P

Photograph 25 – Internal wall between store room and Guild Cottage (the existing dwelling) to the rear of the storeroom



Photograph 26 - Internal wall between store room and the bottle room of the club to the right side of the storeroom




Photograph 27 – Existing original timber floor joist



Photograph 28 – Existing timber floor boards



Photograph 29 – Rotten floor proposed to be repaired like for like




320110529P

Photograph 30 – Left Side Elevation



Photograph 31 – Front Elevation



0529P

Photograph 32 – Right Side Elevation