

Appendix A- Castle Museum- Defective Lintels

Window 001- Lintel Replacement necessary



(Image 001)



(Image 002, Horizontal split in stone)



(Image 003, further cracking to lintel)



(Image 004)



(Image 005)

Window 002- Repair if possible



(Image 006, Vertical Crack running through

lintel and masonry above)



(Image 007, Cracking through stone lintel)

Window 003- Stitch Repair if possible



Image 8 (Front Elevation, Window

No.3)



Image 009 (Visible crack on underside of lintel)



Image 010 (Straight-edge showing 15mm deflection in lintel)



Image 011 (Crack visible from front face of lintel)

