

320180775P

Design/ Access and Heritage statement for rebuilding of garden wall to Rock House

The property is listed although there is no particular mention of the garden wall in the listing entry; the rear wall is limestone and has collapsed as a result of pressure from a tree which has now been removed.

The existing wall was a drystone wall and the proposed wall has been designed with current Eurocodes for retaining walls and will be faced with the existing limestone walling. In appearance the wall will appear as the existing wall.