


Remove, re-centre and re-bed all ridge tiles to the roof of the barn. Approximately 12 no ridge tiles to be re-bedded. Allowed for provision of suitable access for use in the roof works to the barn due to fragile asbestos roof covering requiring extensive scaffolding otherwise.

This Drawing & Design are copyright and may not be produced without the written consent of The J.Y.M.


Partnership
2. DO NOT SCALE - Use Figured Dimensions Only,
3. The CONTRACTOR is to check and verify all Figured Dimensions Only,
3. The CONTRACTOR is to check and verify all Figured Dimensions of the Contractor of the Contractor

KEY Proposed Works Area



Allow for removal of the existing rotting tongue and groove boards that have been used as a

Proposed removal of remnants of existing timber window between the stone mullion and replacement with new timber. Currently the existing sill has completely rotted through and the timber jambs are also rotten. Further detail available in the specification in section 3.00 schedule of works and the joinery report.



First Floor Barn (1:50 at A3)



Oak House 28 Sceptre Way Bamber Bridge Preston PR5 6AW Tel: 01772 323666 Fax: 01772 338611 Email : jym@jympartnership.co.uk www.jympartnership.co.uk

project: BRABINS SHOP

BRABINS CHARITABLE TRUST

drawing title:

PROPOSED WORKS TO

scale:		
1:50 at A3		
drawn:	checked:	
LM	СВ	
date: AUGUST 2020	•	
project no. 1912	drg. no. 03	rev.