



Photo 1: rear slope



Photo 2: Internal roof space showing worn timber



Photo 3: Internal roof space showing water egress



Photo 4: Internal roofspace showing perished stone slates



Photo 5: photo showing damaged purlin