



IN17 - Timber ridge support dangerous and anticipate collapse upon further degradation of planks



IN18 – Timber ridge support severely deflecting, and roof layout skewed in response to movement and lack of support – infrequent or nonexistent collar ties