



IN19 - Blockwork rebuilt at eaves, suspect due to original failure of roof.