



IN20 – Eastern section elevation facing south, severe distortion, vertical cracks and inappropriate repointing





IN21 – Eastern section elevation facing south, failed collar tie at roof, severe cracking and distortion, inappropriate in-fills