



Entering site office and wall to be removed, note storm damage to roof



Side elevation building demolished, proposed reduced 3.2 m. Not secure



Rear elevation building width reduced 3.2 m



Elevation to field silo, portacabin, lorry and wall removed



Front from field silo,office,loo removed wall changed to stone



Internal structure quad storage not secure



Internal wall finish machine storage not secure



Storm damage



View from proposed living room up hill



View from proposed patio uphill wall rebuilt with stonework