

Project details

Job no.	LTC115
Site	Talbot Hotel, Talbot Street, Chipping, PR3 2QE
Client	Sunderland Peacock & Associates Ltd.
Arboriculturist	Jennie Keighley PhD MSc MArborA
Local authority	Ribble Valley Borough Council
Issue date	2 February 2022

Lakeland Tree Consultancy
Halton Mill, Mill Lane
Halton, Lancashire
LA2 6ND

T: 01524 874124

E: info@lakelandtreeconsultancy.co.uk

W: lakelandtreeconsultancy.co.uk



Summary

- The client, Sunderland Peacock & Associates Ltd., instructed Lakeland Tree Consultancy to survey the trees at the above site in relation to a planning application for the conversion of the existing public house and barn into residential dwellings.
- Trees potentially within influencing distance of the proposed works were surveyed in accordance with the British Standard guidance outlined in BS5837: 2012 *Trees in relation to design, demolition and construction Recommendations* on 28 January 2022.
- The survey identified three individual trees, two groups of trees and one woodland edge, which were located both within the site and on areas of immediately adjacent land.
- Details and locations of the existing trees in relation to the existing site are included in the tree survey schedule and on the tree survey plan, below. These documents should be used to inform the design process in accordance with BS5837: 2012.



BS5837 Tree Survey Schedule

The trees surveyed have been assigned one of the following categories, in line with the guidance outlined in British Standard 5837 (2012)

Trees in relation to design, demolition and construction - Recommendations: -



Trees of high quality with an estimated remaining life expectancy of at least 40 years



Trees of moderate quality with an estimated remaining life expectancy of at least 20 years



Trees of **low quality** with an estimated remaining life expectancy of at least 10 years, or young trees with a stem diameter below 150mm



Unsuitable for retention

Those in such a condition that they cannot realistically be retained as living trees in the context of the current land use for longer than 10 years

Key to tree survey schedule: -

T G W H	Tree Group	Age is classed as either: young; semi-mature, early-mature, mature or post-mature
	Woodland Hedge	Life expectancy is classed as either: <10 years; 10+ years; 20+ years or 40+ years
DDA	Root protection area Estimated values	The radial RPA is calculated as twelve times the stem diameter and represents the area where protection of the tree roots during development works is essential to the tree's future health and survival
RPA		Where the RPA is not shown as circular on the tree survey plan, it may have been modified to take account of built structures such as buildings, roads or retaining walls
#		Measurements may have been estimated where the tree is inaccessible, such as if it is located on neighbouring land or if the stem is heavily covered in ivy
		Where trees have multiple stems, an average stem diameter may be given
	Car arauna of traca and	hadran managements for the largest individual will be given as every representations of he given where the

≤≥≈ For groups of trees and hedges, measurements for the largest individual will be given or average measurements may be given where the individuals are approximately uniform

BS583	37 Tree survey sc	hedule										
Site	Talbot Hotel, Talb	Surveyor		Jennie Keighley PhD MSc MArborA			Survey date	28 January 2022				
Client	Sunderland Peace	and Peacock & Associates Ltd.					Conditions Overcast, gentle breeze			Job no.	LTC115	
ID no.	Species Latin name	Stem diameter (mm)	Age	Height (m)#	Crown spread (m)	Crown clearance (m)	Structural condition Physiologic condition	dition Life Radial BS5837 expectancy RPA category ological (years) (m)			Genera	l observations
T1	Sycamore cer pseudoplatanus	1110 1140	Mature	28	N 9.5 E 9.5 S 9.5 W 9.5	6	Good	20+	15	В	 Bifurcates near base into two codominar stems Heavy ivy cover to mid-crown has been partially cleared to allow inspection of ba and lower stem Significantly crown lifted in the past, leav wounds to a diameter of 300mm, many of which are fully occluded, but some of which have significant decay cavities Floodlight and wire attached to north mid stem of eastern leader 200mm diameter secondary branch failuren eastern leader at a height of 12m with another 100mm branch failure nearby Occasional minor deadwood throughout crown 	
T2	Japanese cherry Prunus serrulata	160	Mature	3	N 2.5 E 2.5 S 2.5 W 2.5	1.5	Good	10+	1.92	С	Weeping varietyCrown reduced in	the past



Site	Talbot Hotel, Talbot	Surveyor Jennie Keighley PhD MSc MArborA				Survey date	28 January 2022						
Client	Sunderland Peacoc	k & Asso	ciates L	td.		Condition	ions Overcast, gentle breeze				Job no.	LTC115	
ID no.	Species Latin name	Stem diameter (mm)	Age	Height (m)#	Crown spread (m)	Crown clearance (m)	Structural condition Physiological condition	Life expectancy (years)	Radial RPA (m)	BS5837 category	General observations		
T3	Sycamore Acer pseudoplatanus	850 800 400 #	Mature	26	N 9.5 E 9.5 S 9.5 W 9.5	4	Good Good	20+	14.8	A	 Located on edge of river bank, which prevents detailed inspection Trifurcates near base Moderately light ivy cover growing to mid-crown inhibits detailed inspection base and stems Crown lifted in the past; wounds partially occluded 		
G1	≈ 7no. common ash Fraxinus excelsior	≤ 300 #	Semi- mature to early- mature	≤ 16	N ≤ 4.5 E ≤ 4.5 S ≤ 4.5 W ≤ 4.5	≥ 1.25	Poor	<10	≤ 3.6	U	group along r Crowns exhib advanced dec infection with dieback disea fraxineus)	iting signs of mid-stage to cline due to terminal fungal pathogen ash use (<i>Hymenoscyphus</i> neavy ivy cover growing to	
G2	≈ 5no. sycamore	≤ 300 300 300 300	Early- mature to mature	≤ 20	N ≤ 6 E ≤ 6 S ≤ 6 W ≤ 6	≥ 1.5	Good	20+	≤ 7.2	В	 Most of trees 	growing along river bank multi-stemmed from base neavy ivy cover growing to	

Good



upper crowns

Acer pseudoplatanus


300


#

W ≤ 6

BS5837 Tree survey schedule												
Site	Talbot Hotel, Talbot Street, Chipping, PR3 2QE					Surv	/eyor Je	ennie Keighley PhD MSc MArborA			Survey date	28 January 2022
Client	Sunderland Peace	ock & Ass	sociate	es Ltd.		Con	ditions O	vercast, gentle breeze			Job no.	LTC115
ID no.	Species Latin name	Stem diameter (mm)	Age	Height (m)#	Crown spread (m)	Crown clearance (m)	Structural condition Physiologica condition	Life expectancy I (years)	Radial RPA (m)	BS5837 category	Genera	l observations
W1 F Cr	Common ash Hawthorn Holly European beech Common oak Common alder Blackthorn Bird cherry Field maple Hazel Fraxinus excelsior rataegus monogyna Ilex aquifolium Fagus sylvatica Quercus robur Alnus glutinosa Prunus padus Acer campestre Corylus avellana	≤ 200	Young to mature	≤ 15	N ≤3 E ≤3 S ≤3 W ≤3	≥ 0	Poor to Good	40+	≤ 2.4	C	not accessed to inSouthern edge of young to semi-maA significant comp	a mixed, predominantly ture copse conent is evidently ash symptoms of terminal







Tree Survey Schedule Summary Species Cat. ID No. Sycamore T1 В Cherry T2 C Sycamore T3 Α ≈ 7no. ash G1 U ≈ 5no. sycamore G2 В W1 Various C

Tree Survey Plan

BS5837 Tree retention categories:











Identification numbers:

T = individual tree G = group of trees H = hedge W = woodland

Site:

Talbot Hotel Talbot Street Chipping PR3 2QE

Client:

Sunderland Peacock & Associates

Date: February 2022
Scale: 1:500 at A3
Drawing: LTC115-TSP

Drawn by: JK



Halton Mill, Mill Lane, Halton, LA2 6ND info@lakelandtreeconsultancy.co.uk 01524 874124

lakelandtreeconsultancy.co.uk