



EXISTING FRONT ELEVATION




WALL CONSTRUCTED FROM RANDOM STONE
(NOTE: wooden lintel above garage door rotting and needs replacing)


EXISTING SIDE ELEVATION



EXISTING PLAN VIEW



PROPOSED FRONT ELEVATION



WALL CONSTRUCTED FROM RANDOM STONE
(wooden lintel to be replaced by reclaimed stone lintel)

PROPOSED SIDE ELEVATION



(concrete lintel to be replaced by stone lintel and sill)

PROPOSED PLAN VIEW

