

STRUCTURAL REPORT

**PEWTER HOUSE FARM,
CARR LANE, BALDERSTONE,
RIBBLE VALLEY BB2 7LN**

Prepared by: Adam Hirst BEng (Hons) CEng MICE MIMMM
Chartered Civil Engineer
(UK Engineering Council reg.no: 523486)



CONTROL SHEET

CLIENT: Pewter House Developments Ltd
PROJECT TITLE: Pewter House Farm, Carr Lane, Balderstone
REPORT TITLE: Structural Survey Report (Class Q Application)
PROJECT REFERENCE: 22111

Issue and Approval Schedule:

ISSUE 1 <STATUS>	Name	Signature	Date
Prepared by	Adam Hirst		31.08.22
Reviewed by	-		
Approved by	Adam Hirst		31.08.22

Revision Record:

Issue	Date	Status	Description	By	Chk	App
2						
3						
4						
5						
6						
7						
8						

CONTENTS

Page No.

1.0	Introduction	4
2.0	Findings	5
3.0	Summary & Conclusions	6

Appendix A: Photographs

1.0 Introduction

Fusion CSE Limited was appointed by Pewter House Developments Limited to carry out a structural survey of an existing agricultural building (used as barns), with a view to determining the feasibility of converting the building to a habitable dwelling.

The inspection consisted of a visual inspection only. No intrusive investigation was carried out and only areas that were readily visible and without obstruction were inspected.

2.0 Findings

The barns consist of three duo-pitched steel portal frame structures which adjoin each other and are partially sheeted. Each structure consists of four bays (see photograph 1).

There is some blockwork and some timber infill between columns at lower level (see photograph 4) and in the absence of vertical bracing, it is considered that this is providing some longitudinal stability.

Existing roof purlins are timber, spanning between frames, and the roof covering is corrugated fibre cement panels (refer to photographs).

Foundations are unknown and at ground level the covering is mainly concrete hardstanding (depth and make-up unknown) and raised plinths with some areas unfinished (see photograph 3).

3.0 Summary & Conclusion

The writer considers that the buildings are capable of conversion to habitable space with limited structural work, which could be carried out within the existing building footprint and without significantly impacting on the existing structure.

Some local strengthening of existing structure may be required, subject to architectural proposals and detailed design.


Foundations will need to be investigated and, depending on the final form, some improvement works may need to be considered.

The structure currently relies on infill panels, sheeting and connections for stability. Some additional stability bracing may be required following detailed structural assessment.

Appendix A: Photographs



1. Portal frames – concrete hardstanding, timber purlins, 4 bays



2. Portal frame – mid structure, timber infill between columns



3. Portal frame – unfinished ground



4. Infill between columns longitudinally – timber sleepers and blockwork

Standard Terms

- 1) This report is the property of Fusion CSE Limited and is confidential to the client designated in the report.
- 2) Whilst it may be shown to his/her professional advisors, the contents are not to be disclosed to, or made use of, by any third party, without our express written consent. Without such consent we can accept no responsibility to any third party.
- 3) We will consider the re-issue of the report in its original form to a third party within 6 months of the original report date for an administrative fee (currently £50.00 excluding VAT). Upon lapse of a 6-month period the report can only be re-issued following a full reinspection, which will attract a full survey fee.
- 4) We reserve the right to refuse copies of the report to any third party (other than those named above). We also reserve the right to amend our opinions in the event of additional information being made available at some future date.
- 5) Whilst every effort will be made to fully inspect those parts of the building requested of us, no permanent or secured fixtures and fittings will have been removed. We will not have inspected woodwork or other parts of the structure which were covered, unexposed or inaccessible and we are unable to report that any such part of the property is free from defect.
- 6) External elevations and the roof will be viewed from ground level, using binoculars where necessary.
- 7) In the event that defects have been purposely concealed and not disclosed, for instance by recent re-decoration or placing of furniture, Fusion CSE Limited shall not accept responsibility or consequence for resulting undetected defects.
- 8) Our inspection will not research the presence, or possible consequences, of contamination of the ground or buildings by any harmful substance. Many building materials in the past have contained asbestos, and our inspection will not therefore comment upon asbestos as this cannot be readily identified by a purely visual inspection. Should the client have concerns on this aspect then we would recommend that an independent specialist survey for asbestos is commissioned.
- 9) We will not inspect plumbing, heating, electrical or gas installations, or the internal condition of any chimney, boiler or flue, and would recommend that these are inspected separately by suitably qualified people.
- 10) We will not carry out a Flood Risk Assessment of the property unless specifically agreed in writing before carrying out the inspection.
- 11) Fusion CSE Limited certify that they have carried out the works contained herein with due care and diligence to their best belief and knowledge based on the time and information available. Any report is based on an opinion in respect of the property at the date of inspection. It is not a guarantee that nothing will change in the future.
- 12) This report is made on behalf of Fusion CSE Limited. By receiving it and acting on it, the client – or any third party relying on it – accepts that no individual is personally liable in contract, tort or breach of statutory duty (including negligence).