



3/2024 |
0539 +
0540
5/17/2024

This shows the staircase down from the 3rd floor to the 2nd floor.

The fireproof division of the properties will go between the 2 asterisks. It will NOT be secured at any point to the original oak staircase that starts at this level and goes down to the ground floor.



3/2024/0539
+ 0540
5/7/2024

A fire door will replace this door on the 2nd floor landing. At present it is just closing off a corridor between the 2 rooms on the 2nd floor.



3120241

0539

-e 0540

This shows the corridor between the 2 rooms from the other side. ie with the door open. The fire door will replace the door at this point.

7/4/24, 3:49 PM

2nd floor front

Photo - Google Photos



3/2024/
0539
A 0540
5/17/2024

State of the room at present!



- Download Shift+C
- Rotate left Shift+F
- Add to album
- Add to shared album
- Order canvas print
- Order photo prints
- Archive Shift+A
- Move to Locked Folder

31 2024/0539
 + 0540
 5/7/2024

This doorway will be left as it is but the door will be removed providing access from the 3rd floor to the new fire exit. The arrows mark where an old doorway once (pre 1985) existed. This will be opened up to provide access between the two properties at 2nd floor level.

3 12024/0539
+ 0540
51712024

