

Photographic Record (1.5m graded staff for scale)



Main east elevation of barn



Rear west elevation of barn



North gable of barn showing tear crack to east corner washed out walltops to main barn.



South gable of barn showing more recent central doorway, with blockwork jambs. Also note blocked pitching window above and blocked shippon doorways either side, lost southeast corner and washed out walltops.



North end of east elevation showing vent slits to both floors and threshing doorway with lost voussoir to arched lintel and diagonal crack across the corner. Also note previously repointed cracking to high level.



South end of east elevation showing blocked doorway and pitching window above. Also note missing masonry and washed out pointing at ground level.



Missing stone voussoir to arched lintel and date stone above.



Lost masonry to southeast corner of the barn, viewed from the east side



Lost masonry to southeast corner of the barn, viewed from the south side. Also not previously blocked doorway to shippon.



Southwest corner of outshut showing crack to the right of partially blocked window on south return wall.



East return wall of oushut at abutment with the west wall of the main barn, showing crack at abutment and blocked doorway with reused lintel to head.



View of south west corner of main barn and south return of oushut. Note crack to unbonded masonry at abutment.



View of northwest corner of main barn and abutment with north return to oushut showing cracking to main barn and at unbonded abutment with oushut.



South end of oushut and main barn showing slipped and missing slates at verge and ridge including plant growing out of the wall top to main barn. Also note hairline cracking at high level to both walls.



View of north jamb of threshing doorway . Note footing for lost threshing doors.



North end of east wall to main barn internally. Showing cracking from wall head to either side of the doorway.



Arched timber lintel to doorway in west wall opposite threshing doorway through into outshut. Note hairline cracking the masonry above,



North side of doorway into outshut showing crack at abutment of main barn and outshut and fixing at head for lost doors.



General view of the main barn looking north.



General view of the main barn looking south.



Cracking to northwest corner of main barn hidden behind stored items.



Outshut looking to southwest corner showing failed and partially supported half truss. Also note blocked openings to south wall beyond.



View of roof structure looking north, showing additional support to ties of end two trusses and decay from water ingress to head of truss beyond.



Viewed of decayed head to truss as a result of loss of ridge stones.

Opposite, individual views of bays to main barn roof structure.



North end bay
east side



North mid bay
east side



North central bay
east side



South central bay
east side



South mid bay
east side



South end bay
east side



North end bay west side



North mid bay west side



North central bay west side



South central bay west side



South mid bay west side



South end bay west side