



Ref: S1 Bonstone Brook



Upstream and downstream images. The land falls significantly to the downstream. The applicant and residents at Stone Fold have never witnessed flooding. No flooding in Storm Desmond.

Ref: S2



Minor drainage culvert. Downstream land falls approx. 4 metres within 10 metres of the culvert. No flooding of road ever recorded.

Ref S3



Minor drainage culvert. Land level falls steeply downstream. No history of flooding ever recorded.

Ref S4



Ref: S4

Un-named stream. Land falls sharply downstream. Site has experienced flooding to approx. 10mm in storm events.