



**Crane Wood Farm Barn
PHOTOGRAPHIC RECORD 2025**

For Robbie Taberner and Hannah Grummett

**JAMES INNERDALE
ARCHITECT & HISTORIC BUILDINGS CONSULTANT**

5 Gildersbank, Clapham, Lancaster, LA2 8EG. T. 07743100941 E. jamesinnerdale@yahoo.co.uk

Photographic Record (1.5m graded staff for scale)



Main south elevation of the barn; showing recent threshing doors in the original opening and stoned up byre doors to either side. Consent for threshing doors included retrospectively.



Side / east elevation of the barn



Southwest corner of the barn with C20th lean-to blockwork shippon attached to the west gable, but not included in this application.



View from the north side of the farmyard showing the barn to the right and the rear of the listed farmhouse beyond.



View of east approach to the farmyard showing the listed farmhouse to the left and the east gable of the barn to which this application related to the back.



Blocked left hand / west byre door



Blocked right hand / east byre door



South window to east elevation showing concrete head and cill and roughly built brickwork to the jambs.



Central window to east elevation showing concrete head and cill and brickwork to the jambs.



North window to east elevation within earlier door opening. Concrete cill and cement render over brick jambs and timber lintel.



Doorway to east side of northern shippon with original stone surround.



Slate roof to the north shippon with asbestos and cement fibre roof sheets to main barn above.



Lower section of shippon roof showing abutment with adjoining C20th barn. Note valley gutter appears to have no outlet.



View from central threshing floor with west byre and hayloft over to the left and northern threshing door through into the lean-to shippon the back.



View from central threshing floor with east byre and hayloft over to the right and northern threshing door through into the lean-to shippon the back.



View to east side of the main barn from the central threshing floor. C20th hayloft over on steel beam. Note C20th plasterwork to the walls of the byre and exposed rubble work above, with diagonal crack to upper left hand side reflecting crack externally.



View to west side of the main barn from the central threshing floor. C20th hayloft over on steel beam. Note C20th plasterwork to the walls of the byre and exposed rubble work above with cracking towards verge to upper left and right hand sides. Also note water damage and split to right hand / north bearing of the west truss.



East and west king post trusses viewed from the east with remaining purlins and asbestos and fibre cement sheet roofing over.



View of lean-to shippon from the east door showing threshing door through into the main barn to the left. Note timber half truss to the front and replacement steel beyond.



Northwest corner of north shippon, with doorway to C20th shippon to left and window opening to modern barn to the north. Note mix of cementitious plaster and earlier layers of limewash to the walls.



Doorway from north shippon, into modern barn beyond.



Window to north wall of north shippon with lower cementitious plaster and limewash above. Also note decay to the timber lintel.



Doorway to east side of north shippon.



East end bay south slope of main barn



West end bay south slope of main barn.



Central bay of main barn south slope to the top and north slope to the bottom



East end bay north slope of main barn



Central bay north slope of main barn



West bay north slope of main barn