

**A** Provide rebated intumescent and smoke seals to the existing doors with either:

- i) An Envirograf Product group 76 Rebated intumescent fire and smoke seals with aluminium holder (sheet 1)
- II) An Envirograf Product group 100 Rebated intumescent fire and fire/smoke seals in two types (sheet 2)

**B** Repair with matching materials, split/damaged panels to panel doors re-using existing plants or made to match plants as req.d.

**C** Replace non fire resistant glazing with new Pyroglas (clear) or Georgian wired glass dependant on location of door

**H** English Heritage Conservation Report 2008 Room reference for Room location