

---

## Threats to the Whalley Conservation Area

24

Continuing loss of original architectural details and use of inappropriate modern materials or details.

Many of the unlisted, and some of the listed, buildings in the conservation have been adversely affected by the use of inappropriate modern materials or details. Common faults include:

- the replacement of original timber sash windows with uPVC or aluminium (e.g. nos. 4-18 King Street; nos. 2-8 and nos. 1-11 Whalley Road;
- the loss of original panelled front doors and their replacement with stained hardwood, uPVC or aluminium doors
- the replacement of stone slate or Welsh slate roofs with concrete tiles (e.g. nos. 20 and 22 King Street (both grade II listed);
- poor quality windows on a listed building (e.g. the Swan inn, King Street; nos. 33 and 35 King Street; Abbeycroft, nos. 1-3 The Sands; nos. 2 and 3 The Square, Church Lane

*Nos. 33-35 King Street*

Continuing loss of existing front boundaries.