



To Chipping Congregational Church

Report on Church doors

After looking at and assessing the doors my conclusion is that it is difficult to draft proof the doors in their present state.

There is some rottenness along the bottom edge of the doors which is virtually impossible to fit draft exclusion to.

Also with them being double doors it is hard to make a seal down the centre due to twisting in the doors. The option of joining them together to make one door would only exaggerate the twist and not improve the situation.

Personally I would suggest making one new solid door and casing to which draft strip could be fitted and a weather seal across the bottom edge. This would also create a much improved access.

Yours Sincerely



320210461P