Environmental Health Consultation Response	Officer	Ken Robinson	
Detail: Haweswater Aqueduct Marl Hill Section	Flare SRU:	046429	
Address:			

Address:				Ribble Valley
Application Ref:	3/2021/0661	Case Officer:	Mr John Macholc	Borough Council www.ribblevalley.gov.uk
Response Ref:	3/2021/0661/ENV/01	Issue Date:	9 August 2021	

General Comments/Observations

- 1.1 The air quality assessment concludes [in part]: Appropriate good practice dust mitigation measures would prevent significant effects occurring at offsite locations. Such measures are considered to be normal good practice that would be adopted by the contractor meeting the requirements of the air quality mitigation measures within the CCoP. These would also be agreed with the local authority prior to construction works commencing
- 1.2 The noise and vibration assessment concludes [in part]: the CCoP includes construction mitigation measures for the management of construction airborne noise and vibration, and specific measures for the school and Lilands barn have also been identified.
- 1.3 The periods over the extent of the project when 24/7 working will be required will require careful site illumination to avoid light pollution affecting both nearby residents and the local wildlife in a deeply rural location. This has been recognised in the construction plans submitted.

Conclusions/Suggested Conditions

- 1.4 The above observations have been provided on the basis of the level of information submitted and the comments contained within this response represent officer opinion only, at the time of writing, without prejudice.
- 1.5 Industry-standard mitigation methods and best practicable means of minimising nuisance are described in the submitted documents and are intended to be utilised: the use of these should be a condition of any approval.

Officer:	Ken Robinson