



RIBBLE VALLEY
STONEMASONRY

Hodder place, Stonyhurst

1 West View Terrace
Billington
Lancashire
BB7 9LT

07825997546
07713338232

18 Jan 2022

Description

The garden wall has been neglected in the past and has suffered from erosion of the lime mortar and ingress of water & tree/ivy roots.

To remedy this we suggest, clearing of all foliage & ivy, removing the loose top-stones & hacking out the joints in the stonework. Re-building fallen & loose areas of stonework in lime mortar, re-pointing stonework & re-bedding top-stones in lime mortar.

Mortar mix : 1 part NHL grey hydraulic lime 3.5 to 3 parts sharp washed sand.

0.00