From:	Contact Centre (CRM) <contact@ribblevalley.gov.uk></contact@ribblevalley.gov.uk>
Sent:	02 July 2022 19: <b>4</b> 5
To:	Planning
Subject:	Planning Application Comments - 3/2022/0532 FS-Case-434003183
Categories:	xRedact & Upload
Name:	
Address:	
Lancashire	
Planning Application R	eference No.: 3/2022/0532
Address of Developme	nt: 39 The Rydings
Langho	
BB6 8BQ	
Comments: The main of building is very close will be impossible for a	The proposed plan shows that the new and therefore, it will not be possible to and therefore it may maintenance of the wall to take place. Any future repairs to the wall such as pointing will
be impossible. Furtherr	· · · · · · · · · · · · · · · · ·
possible to access or vice	ew the side wall. At some point in the near future, the wooden fascia boards on the garage of
will need re	placing. It will not be possible to access the side of the
this essential work. As t	there is no access between the proposed extension and the
repairs to the	would only be possible by taking down the garage wall from the inside of
• •	he wall of the proposed extension being so close to
problems with a lack of	ventilation and possible damp. Such problems will not be able to be seen, causing further
damage.	

From: Sent: To: Subject:	Planning 27 June 2022 14:20 FW: Planning Application Comments - 3/2022/0532 FS-Case-432271858
Categories:	xRedact & Upload
Sent: 25 June 202 To: Planning <plan< th=""><th>nning@ribblevalley.gov.uk&gt;</th></plan<>	nning@ribblevalley.gov.uk>
Name:	Application Comments - 3/2022/0532 FS-Case-432271858
Address:	
Lancashire	
Planning Applicat	tion Reference No.: 3/2022/0532
Address of Develo	opment: 39 The Rydings, Langho BB6 8BQ
and 37m3 side ex	proposed extension is a significant development consisting of approximately 92m3 rear extension tension. The total width is more than half the width of the existing building. It will be built within undaries to 3 properties and have a maximum height of 4.5m.
	do not support this development.
The proposed ext	ension goes against the open plan layout of the estate by:
•	n rear extension all the way to the western boundary fence to the Rydings and in taking all the space between the garage to the and the northern boundary fence to the latest he
unsightly from the	ook acceptable from the road fronting the property the crowded nature of the proposal will be e rear. This impacts both the aesthetics and will be detrimental to the future maintenance the property. Throughout the estate open spaces have been provided between each of the
The application for	orm suggests there is no impact on parking but it should be noted that the
-	show the conservatory extension that has already been constructed in the garden and this

1

The application form suggests there is no impact on trees. However there is very likely to be damage during

construction of the foundations to the roots

supports.
The roof of the proposed extension will be higher than the existing roofline proposed store roof will contrast significantly with that of the adjoining garage especially when it is built immediately adjoining. It is slightly lower in elevation it will be faced with a 5m high brick wall which will tower up to 3m above the existing fence.
A key consideration for any project is the impact on future maintenance. No mention is made in the proposal for rain water goods and dealing with water from the roof structures. Currently one of the downspouts to the existing gutter at the structure is blocked with weeds growing out. This leads to water cascading onto the existing hard flagged surface and ponding of water to the standing water issue is made worse by the gutters to the surcharging.
Because the house owners do not see the problems with their gutters they do not do anything to rectify any problems this may cause. At least the garage gutters to the rear of and are accessible. This begs the question of how the owners of the Rydings will firstly notice a problem with the rain water goods for the proposed extensions and secondly how will they be able to access and rectify any issues. Certainly the lack of space will mean they will not be able to access the roof gutters from their own property.
Similarly no consideration has been given to existing boundary fences. As the fence posts are on the side of nother they have the maintenance responsibility. The existing condition of the fence behind the garage of nother is poor with a number of fence slats loose, missing or not aligned properly. With the proposed extension so close to the boundary it will not be possible to maintain this fence from and would require the co-operation of the owner of nother for access.
Similarly it will not be possible for the owners of notice to see nor to case should the proposed extension be built it will require a large garden shed to be dismantled and moved to allow access.
As any boundary fence maintenance is minimal now it will be non-existing in the future when visibility and access to

Similarly ground works during construction so close to the fences may result in damage to existing fences and

the fences become an issue.