
Photograph confirming location of manhole identified in sewer survey as FWMH, adjacent to no.9 Windy St



Photograph confirming location of manhole identified in sewer survey as FWMH2



Photograph confirming that there is no manhole immediately adjacent to No. 7 Windy St, as detailed on the UU sewar survey plan.



UU Sewar survey plan for sewars adjacent to 7 & 9 Windy Str

