

Lead Apron – Chimney Stack

Photo taken in April.

Since photo was taken, the lead apron has completely come away from the stack and has been taken off the roof.



Proposed new lead apron flashing will be code 4, same to material and grade as current.



























