

IF IN DOUBT - ASK

	suitability must be checked prior to construction if deemed not to be suitable a bespoke headwall will be required
Approx. top of Bank 79.25m	Approx. top of 79.25m
1in100yr TWL 79.066m	
1in30yr TWL 78.614m	1:400
1in1yr TWL 77.932m	
Permanent Water Level 77.535m	
Bed level 77.235m	
Section B-B	

Notes

А	Headwall s66 position amended	DW	09.07.18
Rev	Revision	Ву	Date

