



Ditch issues from a surface water drain at the edge of Edisford Road Car Park.



PHOTO 1: Ditch as it leaves Edisford Road Public Car Park.



PHOTO 2: Drop in ditch level.



PHOTO 3: Ditch as it passes proposed new crossing location. Note how the ditch flows close to the access road edge.



PHOTO 5: View up the caravan site access track. Note direction of the water flow across the road.



PHOTO 4: View upstream towards proposed crossing location.



PHOTO 6: Beginning of culverted section of ditch.



PHOTO 7: Ditch flows under footbridge. Note build up of debris reducing the cross sectional area of culvert.



PHOTO 8: Ditch exiting culvert.




PHOTO 10: Ditch bed level drops sharply and ditch enters culvert prior to discharging to the River Ribble.




PHOTO 9: Large diameter culvert place in stream.



PHOTO 11: Ditch outfalls with a free discharge to the River Ribble.

320120006P

Rev	Date	Revision notes	By
DO NOT SCALE			
Status			
PLANNING			
Project			
HENTHORN ROAD CLITHEROE			
Title			
ANNOTATED EXISTING DITCH PLAN			
 GLADMAN Gladman House Alexandra Way Congleton Business Park Congleton Cheshire CW12 1LB Tel: 01260 288800 Fax: 01260 288801 www.gladman.co.uk			
Drawn By	Publish Date	Scale(s)	
GH	12/2011	1:500@A1	
Project no.	Drawing no.	Revision	
2010-001	640	-	