

SD 63 NE

AIGHTON, BAILEY &
CHAIGLEY

26059

8/164

SD 677 373

Barn approx. 500 metres west of
Bailey Hall

GV

II

Cruck barn, possibly C16th, with walls of sandstone rubble probably C19th, and with slate roof. East wall has a wide entrance with plain reveals and timber lintels. To the left are 2 windows with plain reveals, each having a pitching hole with plain stone surround above. To the left of each window is a door with plain stone surround, with a 3rd similar door at the left. To the right of the main entrance is a window with plain reveals, having a pitching hole with plain stone surround above, and a door with plain stone surround to its left. At the north is a shippon with 3 doors with plain stone surrounds in its north gable. Inside there are 3 cruck trusses on stone pads. The blades are not joined at the apex, but are held together by a collar. They have outriders, and spurs which once supported principal posts. To the north is a roof truss with tie beam, king post, and principal rafters. At the north and south ends are soft wood hay lofts over later shippons.
