

Application 200 1 2 0 8 0 2 P
Date received

Fee paid £

Receipt No:

Council Offices, Chu

Church Walk, Clitheroe, Lancashire.

el: 01200 4251

www.ribblevalley.gov.uk

## Householder Application for Planning Permission for works or extension to a dwelling. Town and Country Planning Act 1990

You can complete and submit this form electronically via the Planning Portal by visiting www.planningportal.gov.uk/apply

## Publication of applications on planning authority websites

Please note that the information provided on this application form and in supporting documents may be published on the Authority's website. If you require any further clarification, please contact the Authority's planning department.

Please complete using block capitals and black ink

It is important that you read the accompanying guidance notes as incorrect completion will delay the processing of your application.

* * *	rame and Address	2. Agent Name and Address
Title: MR&	MRS First name: E	Title: MR First name: DUNCAN
Company (optional):  Unit:  House name:  Address 1:	House House suffix:	Last name: ISHERWOOD  Company (optional): SUNDERLAND PEACOCK ARCHITECTS  Unit: House number: House suffix:  House name: HAZELMERE  Address 1: PIMLICO ROAD
Address 2:		Address 2:
Address 3: W	HALLEY	Address 3:
fown:	CITHEROE	Town: CLITHEROE
County: LA	ancs	County: LANCS
ountry:		Country:
ostcode: SB	7 9SR	Postcode: BB7 2AG

### 3. Description of Proposed Works

Please describe the proposed works:

PROPOSED DEMOLITION OF EXISTING GARAGE AND STABLE
BUILDINGS, AND REPLACEMENT WITH GARAGE BUILDING
LINKED TO HOUSE VIA GLAZED PORCH. RE-SUBMISSION.

3. Descri	ption of Proposed Works (cont	inued)	
I	<u> </u>	Yes No	3201208J2P
If Yes, pleas	e state when the work was started (DD/	_	
Has the wor	k already been completed?	Yes No	(date must be pre-application submissi
If Yes, please	e state when the work was completed {{	DD/MM/YYYY):	(date must be pre-application submission
	ldress Details		5. Pedestrian and Vehicle Access, Roads and Rights of W
ſ	de the full postal address of the applica House H		Is a new or altered vehicle access proposed to or from the public highway? Yes Yes
Unit:		ouse uffix:	proposed to or from the public highway? Yes No. 1s a new or altered pedestrian access
House name:	PEPPER HILL		proposed to or from the public highway? Yes No
Address 1:			Do the proposals require any diversions, extinguishments and/or creation of public
ddress 2:			rights of way? Yes No
ddress 3:			If Yes to any questions, please show details on your plans or drawings and state the reference number(s) of the plan(s)/ drawing(s):
wn:	WISWELL		
ounty:	LANCS		
ostcode ptional):	BB7 9BZ		
ou were give oplication mease tick if the own, and the fficer name: eference:	complete the following information about (This will help the authority to deal wore efficiently) the full contact details are not the remaining the same of the complete as much possible:  Date (DD MM YYYY): pplication submission) pre-application advice received:	ith this	are within falling distance of your proposed development?  If Yes, please mark their position on a scaled plan and state the reference number of any plans or drawings:  Will any trees or hedges need to be removed or pruned in order to carry out your proposal?  If Yes In No lif Yes, please show on your plans which trees by giving them numbers e.g. T1, T2 etc, state the reference number of the plan(s)/drawing(s) and indicate the scale.
Parking			9. Authority Employee / Member
the propos	ed works affect		With respect to the Authority, I am:
ung car par s, please de	king arrangements? Yes		(a) a member of staff  Do any of these (b) an elected member  statements apply to you?
15 547	CHTNIC CAP PARICTNI	<u></u>	c) related to a member of staff d) related to an elected member
AYOUT	HAS BEEN ALTERED, OPOSED LAYOUT PR	BUT	if Yes, please provide details of the name, relationship and role
IE PRO	POSED LAYOUT PR	OVIDES	
Allina	RER OF PARKETIONS	SPACES !!!	
ITHIN	THE GARAGE AND COL	URTYARD.	4

## 10. Materials If applicable, please state what materials are to be used externally. Include type, colour and name for each material: Not applicable Existing Don't Proposed (where applicable) Know RENDER / STONE. RENDER / TIMBER Walls BOARDING PROFICED ROOF SHEETING Roof SLATE. ITILE ROOF Windows TIMBER UPVC Doors TIMBER. TIMBER. **Boundary treatments** V (e.g. fences, walls) TARMAC/CONCRETE Vehicle access and TARMAC. hard-standing Lighting Others (please specify) Are you supplying additional information on submitted plan(s)/drawing(s)/design and access statement? Yes No If Yes, please state references for the plan(s)/drawing(s)/design and access statement:

11. Certificates		The side of the state of the st
One Certificate A, B, C, or D, must	be completed, together with the Agricultural Holdings Certificate OF OWNERSHIP - CERTIFICATE A	cate with this application form
Town and Country Pi	anning (General Development Procedure) Order 1995 Certific	ate under Article 7
I certify/T <del>he applicant certifies</del> that on owner (owner is a person with a freehold	the day 21 days before the date of this application nobody except d interest or leasehold interest with at least 7 years left to run) of any	it <del>biazoit</del> a fire abbiirant mas rise
which the application relates  Signed - Applicant:	Or signed - Agent:	Date (DD/MM/YYYY):
	160	11/09/14
	A CONTINUE OF THE CONTINUE OF	
I certify/ <del>The applicant certifies that  </del> 21 days before the date of this applica	CERTIFICATE OF OWNERSHIP - CERTIFICATE B anning (General Development Procedure) Order 1995 Certificate where the applicant has given the requisite notice to everyone else tion, was the owner (owner is a person with a freehold interest or leading to which this application relates.	e issuisted detown who, on the day i
Name of Owner	Address	Date Notice Served
		·
	Supplemental production of the control of the contr	<i>n</i>
	115	EP 2012
	Control FOR THE	Date (DD/MM//YYY):
Signed - Applicant:	Or signed - Agent: ATTENTION OF	Date (DD) Minia 111).
certify/ The upplicant certifies that: Neither Certificate A or B can be All reasonable steps have been take interest or leasehold interest with at unable to do so. The steps taken were:	ne issued for this application en to find out the names and addresses of the other owners <i>(own</i> least 7 years left to run) of the land or building, or of a part of it—bu	er is a person with a freehold at I have/ th
Name of Owner	Address	Date Notice Served
The state of the s		
A		
1		
Notice of the application has been put (circulating in the area where the land	olished in the following newspaper On the following dissituated):  On the following displays before	ate (which must not be earlier e the date of the application):
		D. (DOJAHADAAA)
Signed - Apolicant:	Or signed - Agent:	Date (DD/MM/YYYY):

I certify/ The applicant certifies that:  Certificate A cannot be issued for the interest of this application, was the of any part of the land to which the steps taken were:	taken to find out the names and addresses owner (owner is a person with a freehold in this application relates, but I have/ the app	ngland) Order 2010 Certificate of everyone else who, on the di terest or leasehold interest with a plicant has been unable to do so	ay 21 days before the t least 7 years left to run)
Notice of the application has been publ (circulating in the area where the land is	ished in the following newspaper s situated):	On the following date (which than 21 days before the date	h must not be earlier e of the application):
Signed - Applicant:	Or signed - Agent:		Date (DD/MM/YYYY):
Āgricu	AGRICULTURAL LAND DECLARA relopment Management Procedure) (Englitural Land Declaration - You Must Comple ation relates is, or is part of, an agricultural	gland) Order 2010 Certificate to Elther A or B	under Article 12
Signed - Applicant:	Or signed - Agent:	-	Date (DD/MM/YYYY):
	P-P LK	~ "	05/09/12
(B) I have/ The applicant has given the rebefore the date of this application, was a as listed below:	equisite notice to every person other than rate and the series of an agricultural holding on all or	nyself/ the applicant who, on th	e day 21 days plication relates,
Name of Tenant	Address		Date Notice Served
Signed - Applicant:	Or signed - Agent:		Date (DD/MM/YYYY):
13. Planning Application Requir Please read the following checklist to malinformation required will result in your apthe Local Planning Authority has been sult The original and 3 copies of a completed and dated application form: The original and 3 copies of a plan which identifies the land to which the application relates drawn to an identified scale and showing the direction of North:	re sure you have sent all the information in plication being deemed invalid. It will not omitted.  The original and 3 copies of a design and access statement if proposed works fall within a	support of your proposal Failu be considered valid until all info The correct fee: The original and 3 cop completed, dated Ow Certificate (A, B, C or D The original and 3 cop	ies of the nership - as applicable):

14. Declaration  I/we hereby apply for planning permission/consinformation.					litional
Signed - Applicant:	Or signed - Agent:	· · · · · · · · · · · · · · · · · · ·		e (DD/MM/YYYY):	
	P.P. L		09	5/09/12 la	iate cannot re-applicatio
15. Applicant Contact Details		16. Agent Co	ontact Details		
Telephone numbers		Telephone num	bers		
Country code: National number:  Country code: Mobile number (optional):	Extension number:	Country code: Country code:	National number	123178	Extensior number:
Country code: Fax number (optional):  Email address (optional):		Country code:  Email address (c	Fax number (optional):	tional):	
17. Site Visit			_		
Can the site be seen from a public road, public for	•	other public land?	Yes	No No	
If the planning authority needs to make an appoir out a site visit, whom should they contact? (Please	itment to carry select only one)	Agent	✓ Applicant	Other (if differ agent/applica	
if Other has been selected, please provide: Contact name:					,
Contact name:		Telephone numb	er:		
Email address:					

Location Plan +NORTH. 143 0m Kemple View The Eaves Existing Garage and Stable building to be demolished 320120802P Riding Ring Kennels Pepper Hill Previously approved replacement dwelling Issues Scale 1:1250 ED**i**NA Digimap

Mapping Ordnance Survey'

4026 – Mr and Mrs Bentley, Proposed Garage at Pepper Hill, Wiswell Photographs showing the existing Garage and Stable buildings at Pepper Hill.





**BAT SURVEY** 

AT
GARAGE AND STABLES
PEPPER HILL
PENDLETON ROAD
WISWELL

DATE AND TIME OF VISIT 12<sup>th</sup> JUNE 2012 8.15 PM

WEATHER CONDITIONS

OVERCAST, SLIGHT BREEZE. 11°C

REFERENCE NO. 4206/3

Survey carried out by:

Lynne Rushworth
Sunderland Peacock & Associates Ltd.
Hazelmere
Pimlico road
Clitheroe
BB7 2AG

THIS SURVEY HAS BEEN CARRIED OUT BY: LYNNE RUSHWORTH WHO HAS COMPLETED THE BAT CONSERVATION TRUST'S 'BATS AND BAT SURVEYS' FOUNDATION COURSE FOR CONSULTANTS, AND 'PLANNING AND PREPARATION OF BAT SURVEYS' COURSE

All British bats and their roosts are legally protected under the Wildlife and Countryside Act 1981, the Countryside and Rights of Way Act 2000 and the Conservation (Natural Habitats) Regulations 2007.

### THE BRIEF

In conjunction with the submission of an application for planning approval, to identify if bats are present in the building and the past or possible future use of the building by bats.

### **BAT LEGISLATION - Summary of offences under the law:**

- Intentionally kill, injure or capture a bat.
- Possess or control a live or dead bat, or any part or derivative of a bat.
- Intentionally or recklessly damage, destroy or obstruct access to any structure or place that a bat uses for shelter or projection whether currently used or not.
- Intentionally or recklessly disturb a bat while occupying a structure or place of shelter or protection. ('Recklessly' is defined as deliberately take unacceptable risk or fail to notice or consider an obvious risk).

### **LIMITATIONS OF REPORT**

<u>NOTE</u>: The absence of bats is near impossible to prove. The bats' high mobility means it is virtually impossible to rule out bats using any type of structure for roosting or habitat for foraging or on a flight path

- External walls and internal rooms inspected from ground level.
- Roof spaces, attics and lofts will only be inspected if safe access is possible.
- Winter surveys will provide limited results. However internal inspection should determine
  if bats have used the building in the previous year.
- Any building whose structure is considered dangerous can only be inspected from a safe distance.

### **EQUIPMENT USED ON SURVEY**

- 'MAGENTA 5' BAT DETECTOR
- BINOCULARS
- HIGH POWERED TORCH
- LADDERS FOR HIGH LEVEL INSPECTION
- CAMERA

### PROPOSED DEVELOPMENT


Demolition of existing garage and stables to be replaced with a new garage.



Garage front and side elevation



Side elevation of stables




Garage and front stable elevation

TYPE OF BUILDING

HOUSE
BARN
X GARAGE
X OTHER

COMMENTS: The garage and stable block are detached buildings in the grounds of Pepper Hill house.



BRICK STEEL X BRICK/BLOCK AND RENDER OTHER  COMMENTS: The garage walls are constructed in block with a brick plinth and a rough render finish externally. The stable block has timber boarded walls.  ROOF CONSTRUCTION SLATE TILE GREY SLATE STEEL FLAT ROOF FELT  COMMENTS: The roof tile on the garage is in good condition. There is a slight roof overhang to the eaves of the building which is boarded to the underside. The stable roof is corrugated steel.  Yes No BAT ACCESS POINTS IN WALLS  COMMENTS: The render on the garage is in good condition. The timber boarding on the stable block is in good condition, no bat access points where found.	LOCATION URBAN SMALL TOWN/URBAN VILLAGE X RURAL/VILLAGE
COMMENTS: The boundary to the road is formed by a hedge as is the North East boundary. There are a number of mature trees within 10 m of the house.  WALL CONSTRUCTION  STONE BRICK STEEL X DRICK/BLOCK AND RENDER  COMMENTS: The garage walls are constructed in block with a brick plinth and a rough render finish externally. The stable block has timber boarded walls.  ROOF CONSTRUCTION  SLATE TILE GREY SLATE STEEL X	COMMENTS: The garage and stable within the Pepper Hill grounds are remote from the village settlement of Wiswell parallel to Pendleton road forming part of a group of four other properties.
WALL CONSTRUCTION  STONE BRICK STEEL X BRICK/BLOCK AND RENDER OTHER  COMMENTS: The garage walls are constructed in block with a brick plinth and a rough render finish externally. The stable block has timber boarded walls.  ROOF CONSTRUCTION  SLATE TILE GREY SLATE X STEEL FLAT ROOF FELT  COMMENTS: The roof tile on the garage is in good condition. There is a slight roof overhang to the eaves of the building which is boarded to the underside. The stable roof is corrugated steel.  Yes No BAT ACCESS POINTS IN WALLS  COMMENTS: The render on the garage is in good condition. The timber boarding on the stable block is in good condition, no bat access points where found	X HEDGEROW
BRICK STEEL X BRICK/BLOCK AND RENDER OTHER  COMMENTS: The garage walls are constructed in block with a brick plinth and a rough render finish externally. The stable block has timber boarded walls.  ROOF CONSTRUCTION SLATE TILE GREY SLATE STEEL FLAT ROOF FELT  COMMENTS: The roof tile on the garage is in good condition. There is a slight roof overhang to the eaves of the building which is boarded to the underside. The stable roof is corrugated steel.  Yes No BAT ACCESS POINTS IN WALLS  COMMENTS: The render on the garage is in good condition. The timber boarding on the stable block is in good condition, no bat access points where found.	
ROOF CONSTRUCTION  SLATE TILE GREY SLATE X STEEL FLAT ROOF FELT  COMMENTS: The roof tile on the garage is in good condition. There is a slight roof overhang to the eaves of the building which is boarded to the underside. The stable roof is corrugated steel.  Yes No BAT ACCESS POINTS IN WALLS  COMMENTS: The render on the garage is in good condition. The timber boarding on the stable block is in good condition, no bat access points where found.	BRICK STEEL X BRICK/BLOCK AND RENDER
TILE GREY SLATE STEEL FLAT ROOF FELT  COMMENTS: The roof tile on the garage is in good condition. There is a slight roof overhang to the eaves of the building which is boarded to the underside. The stable roof is corrugated steel.  Yes No BAT ACCESS POINTS IN WALLS  COMMENTS: The render on the garage is in good condition. The timber boarding on the stable block is in good condition, no bat access points where found.	
the building which is boarded to the underside. The stable roof is corrugated steel.  Yes No  BAT ACCESS POINTS IN WALLS  COMMENTS: The render on the garage is in good condition. The timber boarding on the stable block is in good condition, no bat access points where found.	X TILE GREY SLATE X STEEL
BAT ACCESS POINTS IN WALLS  COMMENTS: The render on the garage is in good condition. The timber boarding on the stable block is in good condition, no bat access points where found.	the building which is boarded to the underside. The stable roof is corrugated steel.
good condition, no bat access points where found.	
Yes No	COMMENTS: The render on the garage is in good condition. The timber boarding on the stable block is in good condition, no bat access points where found.
	DROPPINGS X


COMMENTS: No dropping or staining evidence on the walls or on the ground surrounding the buildings could be found. At 8.30pm the detector picked up bat activity and a single (probably male) Pipistrelle flew over the house from the North east to South west to forage in the trees on the opposite side of Pendleton rd, this flight path activity continued until 8.45pm. The bat was emerging from the trees adjacent to the road to the North east of the property, this species is recorded as roosting in cracks or crevices in trees. The strongest detector signal coming from trees approx 60m from the house

**ROOF SPACE** 

TRUSSED PURLINS FELT

Yes	No
Х	
	Χ
X	

COMMENTS: The garage roof is trussed with felt all in good condition. The stable roof is lined out internally





Garage roof space



Stable roof space

BAT ACCESS POINTS IN ROOF

Yes No X

COMMENTS: There are no access points in the roofs.

BAT SIGNS, INTERNAL

SIGHTED

**DROPPINGS** 

**DETECTOR RESULTS** 

STAINING/GREASE MARKS SUSPECT SUMMER ROOST

SUSPECT WINTER HIBERNACULA

INSECT OR MOTH FEEDING EVIDENCE

=

Yes

No X

X

X

X

X

COMMENTS:

None of the above evidence was found.

No insect remains (feeding evidence) were found

### CONCLUSION

Although bat activity was detected in the trees adjacent to the property the bat did not emerge or enter the buildings and no signs could be found either internally or externally that bats use or have used in the past the buildings in any way. The demolition of the garage and stable block will not pose a threat to any bat population.

#### **RISK ASSESSMENT**

(The level of probability that bats are using the property is calculated on the evidence found.)

### LOW

### NOTES:

When bats are found to be present in a building:

- A DEFRA licence will be required before any building work is undertaken.
- Pointing work should not be undertaken during winter months as hibernating bats might be entombed.
- Work to roof structure should not be undertaken between late May, June, July and August.
- Small areas of wall could be left un -pointed to encourage potential roosting sites.
- Care must be taken when removing existing roof timbers, and any new timbers or treatment of existing timbers must be carried out using chemicals listed as safe for bat roosts.
- NOTE: The onus lies with the applicant to satisfy themselves that no offence will be committed if the development goes ahead.

If bats are ever found during building work, stop work immediately and contact the Bat Conservation Trust or Natural England.

The Bat Conservation Trust 15 Cloisters House 8 Battersea Park Road London SW8 4BG 0845 1300 228 Natural England Cheshire-Lancashire Team Cheshire-Lancashire Team Pier House Wallgate Wigan WN3 4AL