


**APPENDIX 1:  
SITE PHOTOGRAPHY**

**Mill Pond Wall Deterioration**

**Photograph 1: Mill Pond Wall Deterioration – December 2015**



**Photograph 2: Mill Pond Wall Deterioration – December 2015**



**Photograph 3: Mill Pond Wall Deterioration – December 2015**



**Photograph 4: Mill Pond Wall Deterioration – December 2015**



**Photograph 5:**



**Photograph 6:**



**Photograph 7:**



**Photograph 8:**



**Photograph 9:**



**Photograph 10:**



**Photograph 11:**



**Photograph 12:**





**Dismantled Mill Pond Wall**

**Photograph 13: Dismantled Mill Pond Wall Materials**



**Photograph 14: Location of Dismantled Mill Pond Wall**



**Photograph 15: Location of Dismantled Mill Pond Wall**



**Photograph 16: Location of Dismantled Mill Pond Wall**



# Location of Photographs:

