

LeaHough

CHARTERED SURVEYORS

Survey Valuation Design Planning Sales

SUPPORTING PHOTOGRAPHS

To

Listed Building Consent Application

For

Proposed Replacement Windows (9no.)

At

**Lower Beatrix Farmhouse,
Dunsop Bridge,
Clitheroe,
Lancashire
BB7 3BE.**

Prepared by

LeaHough
CHARTERED SURVEYORS



Figure 1: General View of Front Elevation (Facing South East)



Figure 2: General View of Front Elevation (Facing South East)



Figure 3: General View of Rear Elevation (Facing North West)



Figure 4: General View of Rear Elevation (Facing North West)



Figure 5: Window Replacements - Ref: W1 - W3. Two fixed casement windows to either side, of a central window with side hung opening casement.



Figure 6: Window Replacements - Ref: W4 - W5. Left hand side - fixed casement window. Right hand side window with side hung opening casement.



Figure 7: Window Replacements - Ref: W6 - W7. Left hand side - fixed casement window. Right hand side window with side hung opening casement.



Figure 8: Window Replacement - Ref: W8 & W9. Left hand side - fixed casement window. Right hand side window with side hung opening casement.