


Problem tree in St Lawrence's Churchyard



The tree in the context of the churchyard and adjacent properties – looking south



View north from Fell Brow (unadopted road)



Bellying stone wall, adjacent to roadway



Chapel Brow, looking towards Chapel Hill from the churchyard



Detail showing displaced copings