

Drainage Plan

Condition 17/18

320190763P



- Legend**
- foul rest band
 - rain water gully
 - 100mm inspection chamber
 - 150mm inspection chamber
 - 400mm inspection chamber
 - 600mm inspection chamber
 - ⊠ public sewer inspection chamber
 - 100 dia drain run
 - 150 dia drain run
 - electric

existing electric
existing combine public sewer

S.J. Bialochi Limited Building Surveyors
Drawing no 6012a
Scale 1:100
Drainage Detail
Proposed Residential Development On Land At Ribblesdale View Chorburn