
376900E
377000E
377100E
377200E
444800N
444700N
444600N
survey undertaken April 2019
stone wall (ht1.2)
grass
hedge (ht1.5)
fence
bush
el. post
guy
edge of bridge (ht0.2)
stone wall (ht1.2)
cft (ht1)
stone wall (ht1.2)
stone wall (ht1.2)
stone wall (ht1.2)
stone wall (ht1.2)
bridge (ht1.4)
bridge (ht1.4)
bridge (ht1.4


377600E
377700E
377800E
377900E
444600N
444500N
survey undertaken April 2019
stone wall (ht1.2)
grass
bush
el. post
stone wall (ht1.7)
cr1 (ht1)
pipe concr90.90
M2A
M2B
M2C
M2D
M2E
M2F
M2G
M2H
M2I
M2J
M2K
M2L
M2M
M2N
M2O
M2P
M2Q
M2R
M2S
M2T
M2U
M2V
M2W
M2X
M2Y
M2Z
M2A1
N3L
N3M
N3N
N3O
N3P
N3Q
N3R
N3S
N3T
N3U
N3V
N3W
N3X
N3Y
N3Z
N4A
N4B
N4C
N4D
N4E
N4F
N4G
N4H
N4I
N4J
N4K
N4L
N4M
N4N
N4O
N4P
N4Q
N4R
N4S
N4T
N4U
N4V
N4W
N4X
N4Y
N4Z
N5A
N5B
N5C
N5D
N5E
N5F
N5G
N5H
N5I
N5J
N5K
N5L
N5M
N5N
N5O
N5P
N5Q
N5R
N5S
N5T
N5U
N5V
N5W
N5X
N5Y
N5Z
N6A
N6B
N6C
N6D
N6E
N6F
N6G
N6H
N6I
N6J
N6K