

13 York Street, Clitheroe

Room Breakdown of Defective plaster

Entrance Hall	Ceiling	0	%
	Walls	90	%
Front Room	Ceiling	0	%
	Walls	20	%
Rear Room	Ceiling	100	%
	Walls	25	%
Kitchen	Ceiling	100	%
	Walls	100	%
Staircase/Landing	Ceiling	100	%
	Walls (solid)	60	%
	Walls (partition)	100	%
Bedroom 1.	Ceiling	0	%
	Walls	20	%
Bedroom 2.	Ceiling	50	%
	Walls (solid)	50	%
	Walls (partition)	100	%
Bedroom 3.	Ceiling	100	%
	Walls	20	%
Staircase/Landing	Ceiling	100	%
	Walls (solid)	50	%
	Walls (partition)	100	%
Bathroom	Ceiling	100	%
	Walls	50	%
Bedroom 4	Ceiling	100	%
	Walls (solid)	50	%
	Walls (partition)	100	%