



RIBBLE VALLEY
STONEMASONRY

5 Walmsley Brow,
Billington,
Nr Clitheroe,
Lancashire,
BB7 9TT

10 Feb 2021

Description

Ms Cowdall, Hodder Place, Hodder Court, Stonyhurst

Exterior Stonework

The existing lime pointing to all the ashlar stonework, heads, cills, corbels etc is very weathered out and in some places non existent. There have recently been problems with water ingress. We would recommend all stonework to be re-pointed in lime based mortar 3 parts fine washed sharp sand, 1 hydraulic lime to all stone elevations.

0.00

Estimate is Valid for 12 months from date shown.