

Photographic Record of Defects - Part B

Survey DateFriday 30th April 2021Time of Survey10.45am - 12pmWeather ConditionsDry, 9 degrees C

METHODOLOGY OVERVIEW

To provide a more managed approach to identifying any defects, the highway was divided up into several 20 metre long sections, numbered from 1 to 7. Each section was measured using a white tape measure (as is visible in the overview photos for each section).

Section 1 being nearest to the main school entrance point/junction with the main road and section 7 being nearest to the school playing fields where the proposed 3G pitch is to be constructed.

The location of the 7 sections are illustrated on the scale drawing 'SSL2277 12 Highways Condition Survey' which accompanies this document.

A written description and photographic record of the defects within each section is provided below. It should be noted that where there are numerous potholes/defected or deteriorating macadam within close proximity, an overall rectangular area has been identified - in practice should these areas be rectified, an overall rectangle would be cut out and replaced rather than attempting a large number of individual rectifications.

<u>Note</u>

Due to file upload sizes permittable on the Planning Portal, the Photographic Record is divided into two parts:


Part A - records highway sections 1 to 3 Part B - records highway sections 4 to 7

Surfacing Standards Limited. Office 2, Empingham House, Ayston Road, Uppingham, Rutland, LE15 9NY



Description: 60 to 80 metres from the junction off the main road

Overview Photo:



Surfacing Standards Limited. Office 2, Empingham House, Ayston Road, Uppingham, Rutland, LE15 9NY



Area $1 - 4m \times 5m = 20m2$





Surfacing Standards Limited. Office 2, Empingham House, Ayston Road, Uppingham, Rutland, LE15 9NY







T. 01536 400 012 E. info@surfacingstandards.co.uk

www.surfacing standards.co.uk



Description: 80 to 100 metres from the junction off the main road

Overview Photo:



No defects noted

Surfacing Standards Limited. Office 2, Empingham House, Ayston Road, Uppingham, Rutland, LE15 9NY



Description: 100 to 120 metres from the junction off the main road

Overview Photo:



Surfacing Standards Limited. Office 2, Empingham House, Ayston Road, Uppingham, Rutland, LE15 9NY



Area 1 = 1.2m2





Surfacing Standards Limited. Office 2, Empingham House, Ayston Road, Uppingham, Rutland, LE15 9NY



Area $2 = 2m \times 5m = 10m2$





Surfacing Standards Limited. Office 2, Empingham House, Ayston Road, Uppingham, Rutland, LE15 9NY



Description: 120 to 140 metres from the junction off the main road

Overview Photo:



Surfacing Standards Limited. Office 2, Empingham House, Ayston Road, Uppingham, Rutland, LE15 9NY



Area 1: 1m2





Surfacing Standards Limited. Office 2, Empingham House, Ayston Road, Uppingham, Rutland, LE15 9NY



Area 2: 1m2





Surfacing Standards Limited. Office 2, Empingham House, Ayston Road, Uppingham, Rutland, LE15 9NY



Area 3: $4.5m \times 2m = 9m2$













Area 4: 3.6m x 4m = 14.4m2









