



Existing low level wired fencing noted, circa 1.2m in height which straddles the boundary between the school grounds and the neighboring gardens. Noted to provide minor security measure to the side of school.

Existing shrubbery and trees noted to rear of site.

3No. Existing farm style gate and low level transparent timber picket fence offering inadequate security protection from vandals and trespassers alike.

Existing low level fencing noted, circa 1.2m in height which straddles the boundary between the school grounds and the neighboring gardens. Noted to provide adequate security measure to the side of school.

Existing shrubbery and trees noted to rear of site.

Existing low level fencing noted, circa 1.2m in height which straddles the boundary between the school grounds and the neighboring gardens. Noted to provide adequate security measure to the side of school.

Existing low level retaining wall, circa 1m in height offers adequate security protection from vandals and trespassers alike.

Existing low level fencing noted, circa 1.2m in height which straddles the boundary between the school grounds and the neighboring gardens. Noted to provide adequate security measure to the side of school.

Existing low level gate, circa 1.2m in height noted to vehicular entrance. Low level pedestrian access gate noted. Noted to provide minor security measure to the front of school

Series of existing low level gates, circa 1.2m in height noted to vehicular exit. Noted to provide minor security measure to the front of school

Existing farm style gate offering inadequate security protection from vandals and trespassers alike. Requires a new 2m high

