

Inspection History: PWC/20/7913

Mill Farm, Clitheroe, BB7 3JJ

Inspector	Date	Item	Plot
Saira Is-Haq	02/06/2022	<p>Commencement</p> <p>Met with the builder to inspect the commencement of the proposed dwelling to this site address.</p> <p>The builder had demolished the existing garage and was continuing with the excavation (10%) dug out; the ground is poor perhaps a previous landfill sub strata. It also has a sewer running through the proposed building.</p> <p>I have asked the builder to consult with NWW, and carry out a build over and consultation. A drainage connection using band seals to the clay has been undertaken.</p> <p>The next inspection will be further to the NWW consultation when the excavation can continue.</p>	