



DRAINAGE VERIFICATION REPORT

LNT CONSTRUCTION

Site Address: **Ribble Valley Lodge, Whalley Road, Barrow, Clitheroe,
BB7 9GB**

Report Date: 19th December 2024.

CONTENTS 2

Drainage installation photographic evidence 3-5

APPENDICES

CCTV Survey Report A

As Built Drainage plan B

Attenuation tank O&M C

DRAINAGE INSTALLATION PHOTOGRAPHIC EVIDENCE

Fig 1 – Attenuation crate stockpile on site.



Fig 2 – Attenuation Hole excavated filled with bedding.



Fig 3 – Attenuation crates wrapped in impermeable membrane.



Fig 4 – Attenuation crates wrapped in impermeable membrane.



Fig 5 - Fleece protection & Bedding infill around tank.



Fig 6 - Internal drainage pop up installation.



Fig 7 - Internal drainage pop up installation.



Fig 8 - External drainage run installation.



Fig 9 - External drainage run installation.



Fig 11 - Gully installation to carpark as per design.



Fig 10 - External drainage run installation.



Fig 12 - External drainage run installation.



Fig 13- Hydrobrake.



Fig 15 - National Grid Reference of main Foul Water infrastructure.

F01	373861.325	438414.070
F02	373848.076	438418.307
F03	373822.113	438417.472
F04	373798.732	438421.267
F06	373865.116	438415.158

Fig 14 - Flooding route plan




Fig 16 - National Grid Reference of main Storm Water infrastructure.

S02	373850.515	438419.970
S03	373849.261	438415.349
S04	373819.103	438415.503
S05	373800.901	438418.730
S08	373872.508	438446.925

Attenuation Tank.

Sub 1	373825.139	438427.362
Sub 2	373829.653	438427.548
Sub 3	373829.821	438423.051
Sub 4	373825.325	438422.865