

DRAINAGE VERIFICATION REPORT

LNT CONSTRUCTION

Site Address: **Ribble Valley Lodge, Whalley Road, Barrow, Clitheroe,
BB7 9GB**

Report Date: 19th December 2024.



CONTENTS

2

Verification summary

2

Drainage installation photographic evidence

3-5

APPENDICES

CCTV Survey Report

A

CCTV Survey Footage

B

As Built Drainage plan

C

Attenuation tank O&M

D

VERIFICATION SUMMARY

Following a review of the information provided I can confirm that the drainage installation undertaken is as per the approved drainage strategy. The configuration of the attenuation tank has changed minimally to make it rectangular in shape and easier to install, however, the required attenuation volume has still been achieved.

Signed: *I Macdonald*

Print: Iain Macdonald

Position: Civils and Groundworks Contracts Manager.

DRAINAGE INSTALLATION PHOTOGRAPHIC EVIDENCE

Fig 1 – Attenuation crate stockpile on site.



Fig 2 – Attenuation Hole excavated filled with bedding.



Fig 3 – Attenuation crates wrapped in impermeable membrane.



Fig 4 – Attenuation crates wrapped in impermeable membrane.



Fig 5 - Bedding infill around tank.



Fig 6 - Internal drainage pop up installation.



Fig 7 - Internal drainage pop up installation.



Fig 8 - External drainage run installation.



Fig 9 - External drainage run installation.



Fig 10 - External drainage run installation.



Fig 11 - Gully installation to carpark as per design.



Fig 12 - External drainage run installation.

