

APPENDIX 7 - EXISTING PHOTOS



Figure 1 (Building 1) House and attached barn East Elevation



Figure 2 (Building 1) House South East Corner



Figure 3 (Building 1, Building 7) View from South West



Figure 4 (Building 1) View from North



Figure 5 (Building 1, Building 8 to right) View from North West down passage



Figure 6 (Building 2) View from South



Figure 7 (Building 2, Building 9 to right, Building 1 in background left) View from East



Figure 8 (Building 2, Building 1 right) View from West



Figure 9 (Building 9, Building 2 behind Building 5 background left) View from North



Figure 10 (Building 3) View from North. Existing access track in foreground



Figure 11 (Building 3, Building 4 right) View from West



Figure 12 (Building 3) View from East



Figure 13 (Building 3 View from South East)



Figure 14 (Building 3) View from South East



Figure 15 (Building 4, Building 3 right and 1 left) View from East



Figure 16 (Building 4) View from North West



Figure 17 (Building 5) View from North West



Figure 18 (Building 6) View from North