

Larkhill (Old Langho) Maintenance Limited, further images

Index

		Page(s)
1	Proposed access to development - commencement of access, 2021	1
2	Further example proposed access to development	2
3	Further example proposed access	3
4	Proposed access to development - exit view, 2021	4
5	Proposed access - example of insufficient width - Fire Safety concerns	5
6	Proposed access - example (2) of insufficient width - Fire Safety concerns	6
7	Example of likely clash / no passing places	7
8	Area to the rear of No.25	8
9	Example of existing parking on the proposed access route	9
10	Further example of parking to rear of 11-25 Larkhill	10
11	Area to the rear of No.11 adjacent to No.10 (Larkhill owned land)	11
12	Example 2, area to the rear of No.11 adjacent to No.10 (Larkhill owned land)	12
13	Start of track behind Pendle View/Brady Court	13
14	Example 2, start of track behind Pendle View/Brady Court	14
15	Example of current condition of the lane	15
16	Recent example of drainage issues	16
17	Example of blocked drains	17
18	Recent example of parking issues/ existing safety concerns Larkhill	18
19	Example of flooding, area behind No.25 Larkhill	19
20	Example of flooding on proposed access (image still taken from video recording)	20
21	Further example of flooding on proposed access (image still taken from video recording)	21
22	Image of fallen tree on "little green"	22
23	Image (2) of fallen tree on "little green"	23





Further example proposed access to development



Further example proposed access





Proposed access - example of insufficient width - Fire Safety concerns



Proposed access - example (2) of insufficient width - Fire Safety concerns



Example of likely clash / no passing places







Further example of parking to rear of 11-25 Larkhill





Example 2, area to the rear of No.11 adjacent to No.10 (Larkhill owned land)







Example of current condition of the lane




Recent example of drainage issues



Example of blocked drains





Example of flooding, area behind No.25 Larkhill



Example of flooding on proposed access (image still taken from video recording)



Further example of flooding on proposed access (image still taken from video recording) 21



Image of fallen tree on "little green"



Image (2) of fallen tree on "little green"